



Status of Dassault Aviation Instructions for Continued Airworthiness with regards to the ATSRAC recommendations



HWG Task #7 recommendations

- **The final report of HWG Task #7 defined a Standard Minimum Content for the ESWPM :**
 - **Cleaning requirements and methods**
 - **Wire and cable identification**
 - **Wire and cable damage limits**
 - **Installation clamping and routing requirements**
 - **Repair and replacement procedures**
 - **Inspection methods**



HWG Task #7 recommendations

- **Status :**
 - **For maintenance service centers**
 - A "Manufacturing Procedures for Wiring" (MPW) document containing all the information required by HWG Task #7 (except for inspection methods) has been distributed
 - **For every customer**
 - Scheduled inspection procedures contained in the Aircraft Maintenance Manual (AMM) refer to a specific Standard Practices manual.
 - This Standard Practices manual contains only extracts of the MPW
 - The AMM and the Standard Practices manual are part of the Aircraft maintenance documentation



Circuit breakers cycling

- **Falcon Service Advisory documents (service information letters) have been issued in May 2005 for :**
 - **Falcon 50 / 50EX**
 - **Falcon 900 / 900EX / 900EX EASy**
 - **Falcon 2000 / 2000EX / 2000EX EASy**
- **FSAs recommend a cycling of circuit breakers every C inspection (6 years)**
- **Chapter 5 (ICAs) will be updated after acceptance by the operators board**