

## AGING TRANSPORT SYSTEMS RULEMAKING ADVISORY COMMITTEE

---

OFFICE OF THE CHAIRMAN  
KENT V. HOLLINGER  
10309 DUNN MEADOW ROAD  
VIENNA, VA 22182-1325  
(703) 757-3831

February 4, 2004

Mr. Nicholas A. Sabatini  
Associate Administrator  
Regulation and Certification AVR-1  
Federal Aviation Administration  
Room 1000 West  
800 Independence Ave. SW  
Washington, DC 20591

Dear Mr. Sabatini:

At our January 2004 meeting, the Aging Transport Systems Rulemaking Advisory Committee (ATSRAC) reviewed the results of DOT/FAA/AR-01/118 *Aircraft Age-Related Degradation Study on Single- and Three-Phase Circuit Breakers*. After a lengthy detailed discussion, the Committee voted unanimously to make the following two recommendations to the FAA:

1. The FAA should amend Section 9 of AC?? *Development of Electrical Standard Wiring Practices Documentation* (previously recommended by ATSRAC but not yet released) to include circuit breaker maintenance. Manufacturers should consider report DOT/FAA/AR-01/118.
2. The FAA should review ARP 1199 and 4404, and AS 50881 and 5809 for reference into published guidance.

Thank you for your consideration of these recommendations.

Sincerely,



Kent V. Hollinger  
ATSRAC Chairman

Cc: James Ballough  
Brenda Courtney

John Hickey  
Charles Huber